

General Environmental Incident Summary

Incident: 2036 **Date/Time Notice:** 9/5/2013 0925 **DEM Incident No:**
Responsible Party: DL Taylor Inc

Date Incident: 9/5/2013 **Time Incident:** 0915 **Duration:** 12 minutes

County: Stark **Twp:** 139 **Rng:** 96 **Sec:** 1 **Qtr:**

Lat: 46.88620 **Long:** -102.73940 **Method:** Navigation quality GPS

Location Description: 2955 Business Loop East
Dickinson, ND 58601

Submitted By: David Bren

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Jason Patrick
PO Box 1960
Riverton, WY 82501

Distance Nearest Occupied Building: 60 Feet

Type of Incident: Tank Leak

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 95.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Holes in customer passenger saddle tank

Risk Evaluation:

spill was contained on concrete surface, therefore there does not appear to be any environmental impacts

of Fatalities: 0

of Injuries: 0

Affected Medium: 09 - other

Potential Environmental Impacts:

NA

Vin XN473237, US DOT 581706

Motor Carrier ID 292446

Action Taken or Planned:

30 bags of floor dry contained around edge of spill area on concrete only, will clean up area to include floor dry and diesel fuel with sweeper/vac truck.

Wastes Disposal Location: Dickinson Landfill
Aaron Praus / Manager
701-456-7776

Agencies Involved:

Updates

Date: 9/5/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release needs to be followed up on. Please visit the site and confirm cleanup.

Date: 9/9/2013 **Status:** Inspection

Author: Miller, Adam

Updated Volume:

Notes:

Diesel fuel was completely soaked up with floor dry. Waste material was disposed of at Dickinson Landfill. Spill was unable to escape concret pad. No environmental concerns.